

## Product Discontinuation Notices

February 1, 2012

Vision Sensors

No. 2012036E

### Discontinuation Notice of Vision Sensor. Model FZ3-L35[] / Model FZ3-7[][] / Model FZ3-H7[][] / Model FZ3-9[][] / Model FZ3-H9[][] series

#### Product Discontinuation



Model FZ3-L35[]  
Model FZ3-L35[]-10

Model FZ3-7[][]  
Model FZ3-7[][]-10  
Model FZ3-H7[][]  
Model FZ3-H7[][]-10

Model FZ3-9[][]  
Model FZ3-9[][]-10  
Model FZ3-H9[][]  
Model FZ3-H9[][]-10



#### Recommended Replacement

Model FZ4-L35[]  
Model FZ4-L35[]-10

Model FZ4-7[][]  
Model FZ4-7[][]-10  
Model FZ4-H7[][]  
Model FZ4-H7[][]-10

Model FZ4-11[][]  
Model FZ4-11[][]-10  
Model FZ4-H11[][]  
Model FZ4-H11[][]-10

**Discontinuation date : The end of September, 2012**

#### Caution on recommended replacement

About the use of the remodeling software

It is necessary to verify the operation if the remodeling software before FZ4 is used.

Please inquire of the trading company dealing our products including the version up to the remodeling software.

### Difference from discontinued product

Model	Body Color	Dimensions	Wire connection	Mounting Dimensions	Characteristics	Operation ratings	Operation methods
FZ4-L35□	**	**	**	**	**	**	**
FZ4-L35□-10	**	**	**	**	**	**	**
FZ4-7□□	**	**	**	**	**	**	**
FZ4-7□□-10	**	**	**	**	**	**	**
FZ4-H7□□	**	**	**	**	**	**	**
FZ4-H7□□-10	**	**	**	**	**	**	**
FZ4-11□□	**	**	**	**	**	**	**
FZ4-11□□-10	**	**	**	**	**	**	**
FZ4-H11□□	**	**	**	**	**	**	**
FZ4-H11□□-10	**	**	**	**	**	**	**

\*\* : Fully compatible

\* : The change is a little/Almost compatible

-- : Not compatible

- : No corresponding specification

## Product Discontinuation and recommended replacement

Product discontinuation	Recommended replacement
FZ3-L350	FZ4-L350
FZ3-L355	FZ4-L355
FZ3-L350-10	FZ4-L350-10
FZ3-L355-10	FZ4-L355-10
FZ3-700	FZ4-700
FZ3-705	FZ4-705
FZ3-750	FZ4-750
FZ3-755	FZ4-755
FZ3-700-10	FZ4-700-10
FZ3-705-10	FZ4-705-10
FZ3-750-10	FZ4-750-10
FZ3-755-10	FZ4-755-10
FZ3-H700	FZ4-H700
FZ3-H705	FZ4-H705
FZ3-H750	FZ4-H750
FZ3-H755	FZ4-H755
FZ3-H700-10	FZ4-H700-10
FZ3-H705-10	FZ4-H705-10
FZ3-H750-10	FZ4-H750-10
FZ3-H755-10	FZ4-H755-10
FZ3-900	FZ4-1100
FZ3-905	FZ4-1105
FZ3-950	FZ4-1150
FZ3-955	FZ4-1155
FZ3-900-10	FZ4-1100-10
FZ3-905-10	FZ4-1105-10
FZ3-950-10	FZ4-1150-10
FZ3-955-10	FZ4-1155-10
FZ3-H900	FZ4-H1100
FZ3-H905	FZ4-H1105
FZ3-H950	FZ4-H1150
FZ3-H955	FZ4-H1155
FZ3-H900-10	FZ4-H1100-10
FZ3-H905-10	FZ4-H1105-10
FZ3-H950-10	FZ4-H1150-10
FZ3-H955-10	FZ4-H1155-10

## Operation ratings

Product discontinuation Model FZ3-9[ ] / Model FZ3-9[ ]-10 Model FZ3-H9[ ] / Model FZ3-H9[ ]-10	Recommendable replacement Model FZ4-11[ ] / Model FZ4-11[ ]-10 Model FZ4-H11[ ] / Model FZ4-H11[ ]-10
<p>CPU is different. Both the function and the performance are upper compatibilities.</p>	